




1/2" Air Impact Wrench Item No : NC-4277Q



Part List Twin Hammer Type NC-4277Q



No	Part No	Description	Q'ty	No	Part No	Description	Q'ty
1	NC-4277P01	Housing	1	26	NC-4277P26	Ball Bearing	1
2	NC-4277P02	Valve Bushing	1	27	NC-4277P27	Front Plate	1
3	NC-4277P03	Reverse Valve	1	28	NC-4277P28	Cylinder	1
4	NC-4277P04	Spring	1	29	NC-4277P29	Spring Pin	1
5	NC-4277P05	Steel Ball	1	30	NC-4277P30	Rotor	1
6	NC-4277P06	O-Ring	1	31	NC-4277T31	Spring (7 pcs)	1set
7	NC-4277P07	Reverse Lever	1	32	NC-4277T32	Blade (7 pcs)	1set
8	NC-4277P08	Retaining Ring	1	33	NC-4277P33	Rear Plate	1
9	NC-4277P09	Trigger	1	34	NC-4277T34	Ball Bearing	1
10	NC-4277P10	Spring Pin	1	35	NC-4277P35	Packing	1
11	NC-4277P11	Spring Pin	1	36	NC-4277P36	Cover	1
12	NC-4277T12	Muffler Filter (2 pcs)	1set	37	NC-4277T37	Spring Washer (4 pcs)	1set
13	NC-4277P13	Oil Seal	1	38	NC-4277T38	Screw (4 pcs)	1set
14	NC-4277P14	Pin Valve Rod	1		NC-4277T01A	Standard Anvil Ass'y (20,21,22A)	1set
15	NC-4277P15	Spring	1		NC-4277T01B	2" Ext. Anvil Ass'y (20,21,22B)	1set
16	NC-4277P16	Exhaust Deflector	1				
17	NC-4277P17	Exhaust Deflector	1				
18	NC-4277P18	Air Inlet	1				
19	NC-4277P19	Bushing	1				
20	NC-4277P20	Anvil Collar	1				
21	NC-4277P21	O-Ring	1				
22	NC-4277P22A	Anvil	1				
	NC-4277P22B	Anvil (+2")	1				
23	NC-4277T23	Hammer Pin (2 pcs)	1set				
24	NC-4277P24	Hammer Cage	1				
25	NC-4277T25	Hammer (2 pcs)	1set				